

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GR964
ENE
> 1
1.279 mi.
6754 ft.

MANHOLE #55328
EAST 13TH STREET/SHORE PK
BROOKLYN, NY

NY Spills S106721354
N/A

Site 1 of 3 in cluster GR

Relative:
Higher

Actual:
13 ft.

SPILLS:

Name: MANHOLE #55328
Address: EAST 13TH STREET/SHORE PK
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0408111 / 2004-12-28
Facility ID: 0408111
Facility Type: ER
DER Facility ID: 267960
Site ID: 332750
DEC Region: 2
Spill Cause: Unknown
Spill Class: D4
SWIS: 2401
Spill Date: 2004-10-21
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 2004-10-22
CID: 444
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-10-22
Spill Record Last Update: 2004-12-28
Spiller Name: ERT DESK
Spiller Company: MANHOLE #55328
Spiller Address: EAST 13TH STREET/SHORE PK
Spiller Company: 001
Contact Name: ERT DESK
DEC Memo: "10/21/2004 13:05 HRS. Employee REPORTS he FOUND APPROX. 1 PINT UNKNOWN OIL ON APPROX. 100 GAL. WATER IN MH-55328. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO FIRE OR SMOKE. ENV STOP TAG 44553 PLACED. LIQUID SAMPLE TAKEN CLEANUP PENDING PCB RESULTS FROM CHEM LAB. UPDATE: 21-OCT-2004 2017HRS LAB RESULTS LSN # 04-08629-001 < 1.0PPM UPDATE 22-OCT-2004 08:14 HRS. ENVIR. OPER. MECH-A A.GLODOWSKI EMP# 18711 REPORTS: PLACED COAGULANT IN STRUCTURE REMOVED ALL SOLIDS & LIQ. WITH VACTOR. DBL. WASHED STRUCTURE WITH BULL DOG. SUMP FOUND SEALED. STRUCTURE IS MAKING WATER. TAG LEFT IN PLACE PENDING UNDERGROUND CREW COMPLETING WORK. TANKER NEEDED TO KEEP DOWN LIQUID SO WORK CAN BE COMPLETED. DUE TO STRUCTURE MAKES WATER THIS INCIDENT WILL BE TAKEN OFF THE 24hr CLOCK. UPDATE 25-OCT-2004 UG WEST SUPV. L BULLOCK , EMPLOYEE NO 02228 , REPORTS UG REPAIRS COMPLETE, ENVIORNMENTAL TAG NO. 44553, PULLED FROM THE STRUCTURE. JOB IS 100 COMPLETE."

Remarks: "WAITING PCB RESULTS: COMING OFF 24 HOUR CLOCK: 1 PINT OF OIL ON 100 GALLONS OF WATER: CONED # 155910"

All Materials:
Site ID:

332750

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 1094962
Operable Unit: 01
Material ID: 575095
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported